

Temperatur-messbereich / Temperature measuring range / °C	Justagepunkte / Adjustment Points / °C
-20...100	~25 (Ambient)
-20...100	50
-20...100	100
0...250	~25 (Ambient)
0...250	50
0...250	100
0...250	200
150...900	~25 (Ambient)
150...900	50
150...900	100
150...900	200
150...900	300
150...900	500
150...900	900
200...1500	~25 (Ambient)
200...1500	50
200...1500	100
200...1500	200
200...1500	300
200...1500	500
200...1500	900
200...1500	1200
200...1800	~25 (Ambient)
200...1800	50
200...1800	100
200...1800	200
200...1800	300
200...1800	500
200...1800	900
200...1800	1200
200...1800	1800

Justagepunkte / Adjustment Points / °C
~25 (Ambient)
50
100
200
300
500
900
1200
1800